

# Friends of Historic Woolsey

## Our Progress to Date

THANK YOU FOR YOUR SUPPORT!

We couldn't do this without you!



### *Water and Electricity*

Water and electricity are now available on the property.



### *Ground Penetrating Radar*

Ground Penetrating Radar Systems identified the location of unmarked graves. While most of the graves are outside of the cemetery fence, some are located inside.



### *Landscaping and Cemetery Clean Up*

The landscaping project includes a memorial garden, providing a place for reflection. White-flowering, heirloom plants sourced from local families will be planted in the garden. Cemetery maintenance and the cleaning of graves is ongoing.



### *Historic Structure Report*

Landmark Preservation Consulting's Historic Structure Report serves as a restoration guide for the historic church built in 1889.



### *Historic Church Restoration*

Volunteers have made significant progress in the removal of non-historic additions inside the church revealing the church's original window size, original door locations, and the tongue and groove walls. Once completed, the church will provide a much-needed community gathering place. Friends of Historic Woolsey will host open houses for the community to witness the restoration.

